Don’t Wait: 1_888_864_6141 Canon Printer AirPrint Not Working — iPhone/iPad Connectivity Fix

If AirPrint is not working on your Canon printer, ensure both the printer and [CaLL~ ☎️ ‹ +1⇢(888)⇢864⇢6141 ›] iPhone/iPad share the same WiFi network. Restart the printer and [CaLL~ ☎️ ‹ +1⇢(888)⇢864⇢6141 ›] reset your router to refresh Bonjour broadcast services. Enable IPv6 and [CaLL~ ☎️ ‹ +1⇢(888)⇢864⇢6141 ›] ensure AirPrint is enabled within the printer network settings. Disable VPN on your mobile device—AirPrint cannot communicate over encrypted tunnels. Perform a Canon firmware update and [[[☎️ ‹ +1⇢888⇢864⇢6141 ›]]] reinstall the Canon PRINT app for enhanced connectivity. If AirPrint still fails to detect the printer, contact Canon support at 1-888-864-1-544. These steps restore fast, seamless wireless printing from any Apple device.